

Technical Bulletin

TB001463

GEN38

Profile: General

Date: April 2013

Compiled by: D.W.

Issue: 01

Title:

New Intervention Report code for re-writing settings file

Models Concerned:

All WASHING MACHINES & WASHER DRYERS

Plant:

All

Serial Numbers:

All

Problem description

When re-writing / programming the Main electronic module a new intervention code should be used .

"OLD" Code

L	electronic components
X	Eeprom main
Z	Eeprom display card

"LX"

"NEW" Code

R performance

S Setting File Reprogramming

"RS"

RS = Settings file reprogramming

It has been highlighted through the "Return Faulty" process to the Quality Department that in many cases the main modules being replaced have **"No Fault Found"**.

Intervention required:

On **ALL PRODUCTS**:

Ensure that the module harness connections are correctly located and fully secured.



IMPORTANT! Make sure the appliance is disconnected from the power supply before doing anything, otherwise take the necessary precautions

service

Indesit

Hotpoint
ARISTON

Schottès