

# TECHNICAL BULLETIN

Profile: General

TB001141

Issued November 2008

Compiled by C.B.

Indesit Company, Service Department

## Title: Washing-machine / Washer-dryer loose plastic pulley

### Products concerned

All washing-machines and washer-dryers manufactured in Comunanza (industrial part code starting with 80) and Teverola (industrial part code starting with 46).

### Description

Loose plastic pulley

### Work required

If the machine has a loose plastic pulley, do not retighten it but always replace it with a new one in aluminium (see respective code for each model on Service Net)

#### Fault code to be indicated on report

