











NOTE: COMPONENTS MARKED * REFER TO TABLES

	L801	C804	C805	R717	R115	L802	J612	R812	PICTURE TUBE	SUPPLIER CODE
21*	AT4042 /34	330K 250V	7.5K 1.5KV	1R0 1W	33K	L802	-	3P3 1W	VIDEO COLOR	AS1EBV12X01
21*	AT4042 /34	330K 250V	7.5K 1.5KV	2R2 1W	33K	-	X	-	PHILIPS	AS1EAL30X01
20*	AT4042 /30	470K 250V	7.5K 1.5KV	1R0 1W	56K	-	X	-	SAMSUNG PHILIPS	5105822-TC
15*	AT4042 /31	330K 250V	7.5K 1.5KV	2R2 1W	56K	-	X	-	PHILIPS	A36EAH00X01
14*	AT4042 /30	470K 250V	7.5K 1.5KV	1R0 1W	56K	-	X	-	SAMSUNG GOLDSTAR	37GGAB5X-TC 37GGAB5X-TDA34KCD12XX01

	PAL	PAL-SECAM
J48	X	CUT
J49	X	CUT

TUNER R105	TFK 30100UEC 33K	TFK E0000HC 12K	TFK E0000HC 12K
	PAL I	PAL B/G	PAL B/G/D/K
Z100	5Y153 OFNJ 1953	5Y177 OFVG 1958	OFWK 2350
Z101A	5P025B	5P15,3P8	5P15,3P8
Z101B	-	5P15,3P8	5P15,3P8
C125A	120PF	150PF	150PF
C125B	-	-	100PF
C110A	50PF	88PF	88PF
C110B	-	-	88PF
R111	3.3K	3.3K	-
L001	-	1.5MH	-
L101A	X	X	X
L201B	-	-	X
L104A	X	X	X
L104B	-	-	X
R144A	X	X	X
R144B	-	-	X
C240	-	15PF	15PF





IMPORTANT

COMPONENTS MARKED WITH SYMBOL \triangle ARE CRITICAL FOR SAFETY AND MUST ONLY BE REPLACED BY PARTS SUPPLIED OR APPROVED BY THE MANUFACTURER.

